

FIG.1




FIG.2

3/7

INSUFFICIENT SYNC SIGNAL AMPLITUDE (OUTPUT 217 OF COMPARATOR 210)	EXCESSIVE VIDEO AMPLITUDE (INPUT TERMINAL 201)	DETECTION OF AN ABRUPT CHANGE IN PEDESTAL LEVEL (OUTPUT 221 OF COMPARATOR 220)	DETECTION OF NO-INPUT (OUTPUT 222 OF NO-INPUT DETECTING CIRCUIT)	MODE CHANGE
L	L	L	L	SHIFT TO FIRST OPERATION MODE
H	L	L	L	UNCHANGED
L	H	L	L	SHIFT TO FIRST OPERATION MODE
H	H	L	L	SHIFT TO SECOND OPERATION MODE
X	X	H	L	SHIFT TO FIRST OPERATION MODE
X	X	X	H	SHIFT TO FIRST OPERATION MODE

X'DON'T CARE

FIG.3




FIG.4

5/7




FIG. 5




FIG.6

OPERATION MODE	OUTPUT OF MODE MANAGING SECTION 211
FIRST OPERATION MODE	H
SECOND OPERATION MODE	L

FIG.7